



TEST REPORT



250 Chester Street
Painesville, Ohio 44077
Phone: 866-GO-AVERY (866-462-8379)
Fax: 888-358-4469
email: psa.tape@averydennison.com
URL: tapes.averydennison.com

PRODUCT: A915-80
SUPPORT: FLOCK
SUBSTRATE: PP
CERT NO.: 230104 - 1454
FORD ESB M6G17-A
OEM Rev Date: Jul 12
Adhesion Requirements, PSA Antisqueak Flock

NOT FOR NEW DESIGN - NO REPLACEMENT

TAPE REQUIREMENTS:

Table with columns: SECTION, Specification, Results, Status. Rows include sections 3.5 (Fogging, Oil Bath), 3.6.1 (Flock Fiber), 3.6.2 (Flock Adhesive), 3.6.3 (Fabric), 3.6.4 (Pressure Sensitive Adhesive), 3.7 (Thickness), 3.8 (Loose Flock), 3.9 (Abrasion Resistance), 3.10 (Scuffing Resistance), 3.11 (Peel Adhesion), 3.12 (Shear Adhesion), 3.13 (RH Resistance), 3.14 (Heat Resistance), 3.15 (Odor), 3.16 (Flammability).

CERTIFIED BY: [Signature]
Dave Nichols Jr, Automotive Lab Technician

ISSUE DATE: 1-1-24