

250 Chester Street Painesville, Ohio 44077 866-GO-AVERY (866-462-8379) Phone: Fax: 888-358-4469 email: psa.tape@averydennison.com URL: tapes.averydennison.com

TEST R	EPORT
--------	-------

PRODUCT: SA 1123 SUPPORT: **PEU FOAM** SUBSTRATE: ABS 241016 - 0815 CERT NO .:



GMW 16443-TYPE-I

OEM Rev Date: Aug 18 Adhesion Performance Requirements For Adhesive Backed Light Trim and Foam Type I - An adhesive backed foam composite that is entrapped and/or mechanically retained for the life of the vehicle

TAPE REQUIREMENTS:			
3.5.1 Type I Exposure			
SECTION 3.3.3 Edge Adhesion			
3.5.3, Initial, As Received - 24 hrs @ RT			

Specification Securely Bonded

Results Stable, No Lifting or Removal

Stable, No Lifting or Removal

Status Pass

Pass

3.5.4, Heat Aged 168 hrs @ 80°C per ISO 188,

3.5.5, Humidity 168 hrs @ 38°C / 100% RH per GMW 14729 Option

Securely Bonded

Pass

CERTIFIED BY:

David Nichols II, Automotive Lab Technician

ISSUE DATE:

1-1-24

Materials tested to OEM requirements @ 72°F +/- 2°F and 50% RH +/- 5%. Test uncertainty and minor exclusions are available online or upon request. This certificate or report shall not be reproduced except in full, without the written approval of the Avery Dennison® Performance Tapes. Status opinion based upon measurements obtained by personnel with appropriate training and professional experience. This laboratory is not accredited for the calibrations or tests marked *.

Avery Dennison Performance Tapes 250 Chester St. Painesville, Ohio 44077

Original Test Date: 10-16-2024

Page 1 of 1

Securely Bonded

Stable, No Lifting or Removal

	PRODUCT:	SA 1123
Appendix A Table A1	SUPPORT:	PEU FOAM
	SUBSTRATE:	ABS
	CERT NO.:	241016 - 0815

Table A1: GMW16443 Type I Applications Test Data Form

Section	Test	Requirements	Sample	Visual Edge Adhesion
3.5.3 Initial, As Received - 24 hrs			1	Stable, No Lifting or Removal
	Initial, As Received - 24 hrs @ RT		2	Stable, No Lifting or Removal
		_	3	Stable, No Lifting or Removal
3.5.4 Heat	Heat Aged 168 hrs @ 80ºC per ISO 188,		1	Stable, No Lifting or Removal
			2	Stable, No Lifting or Removal
			3	Stable, No Lifting or Removal
3.5.5	Humidity 168 hrs @ 38ºC / 100% RH per GMW 14729 Option B		1	Stable, No Lifting or Removal
			2	Stable, No Lifting or Removal
			3	Stable, No Lifting or Removal

Section	Test	Standard	Requirements	Sample	Result
3.6 Tape Wet Out, GMW15851				1	
	-	85% Tape Wet Out	2		
				3	
Release Liner Contact				1	TBD
	To Be Determined @ Tier	No Lift Prior To Vehicle Install	2	TBD	
				3	TBD
Lin	Liner Removal ISO 8510-2			1	
		Less Than or Equal To 65 N/m	2		
				3	

Aug 18

 $\ensuremath{\mathbb{C}}$ Copyright 2017 General Motors Company All Rights Reserved